

IEQ SCHOOL DATA BASE

School Name: River Hill High School

Principal: Kathryn McKinley

DATE: January 10, 2017

IEQ Team Leader: Napoleon A. Saunders, II

IEQ System Leader: Greg Macuilla

<p>8. Ceiling tiles present; no broken, stained, or painted</p>	<p>Art Rm. 215, 216, Tile 9th Grade Hall, 218, 221, 222, 223, 232A, Humanities Stairwell, Outside 237, 240, 241, Media Storage, Outside electrical room C-242A, 244, 251, cafeteria, café hallway, C-225, 225A, media production room, registrar office, data clerk office, 217, 235, 237, 142, C-202, 203, main gym storage, team room 2, weight room, restroom, locker room, S-103, 100, 154, 152, 151, 149, 145, 123, staff lounge, admin conference, admin office (1), admin</p>	<p>Tile replacement needed {stained or broken} (100, 123, 123A, 145, 149, 154, 200, 203, 204, 215, 216, 217, 218, 221, 223, 232A, 235, 236, 237, S-238, S-103, health room, 240, 241, 244, 246, 251, 254, 255, 9th grade stairwell, 9th grade hallway, Humanities stairwell, Humanities boys restroom, Administrative offices-AP, administrative conference room, cafeteria, cafeteria hallway, kitchen, media center, production room, data clerk office, guidance, registrar office, health room, S-206B, above locker 1428 & 1560, near locker 1429, MST hallway, C-202, main gym, girls locker room and stairwell, weight room, restroom and storage, near C-131, Ives office, book room)</p>			<p align="center">X</p>	<p align="center">20010</p>	<p align="center">2/3/17</p>	<p align="center">2/10/17</p>	
<p>9. Walls show no signs of water damage/mildew/ paint irregularities</p>									
<p>10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.</p>	<p>No violations cited</p>								
<p>11. Limited use of non-issued HCPSS furniture and appliances</p>	<p>100A, 102, 117, 118, 123, 123A, 132A, 134, 138, 141, 142, 143, 147, 149, 152, 153B, 200, 205, 206A, 215, 218, 220, 221, 223A, 233, 234, 235, 238, 239, 240, 241, 249, Media Center, Studio, 206A, Coach's office, Teachers' planning D, Teachers' planning C, teacher planning B, media production</p>	<p>Microwaves (Rm 100A, 102, 117, 123A, 132, 141, 142, 143, 147, 149, 152, 153B, 200, 206A, 215, 220, 239, 240, 241, Media Center, Studio, 206A, Coach's office, Teachers' planning D, Teachers' planning C, teacher planning B); Refrigerators (102, 117, 123A, 132A, 142, 147, 149, 152, 153B, 200, 222, 223A, 238, 239, 241, Coach's Office, Teachers' Planning D, Teacher's planning C); lamps (117, 121, 123, 219, 223, 235, 239, 240); coffee makers (117, 132, 233, 236, 240, teacher planning C); Toaster (Admin kitchen, Guidance workroom); Electric teapot (223A); fan (123, 142, 240, coaches office)</p>	<p align="center">X</p>			<p align="center">2/14/17</p>			
<p>12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.</p>	<p>117, 118, 123, 123A, 134, 138, 143, 200, 205, 218, 221, 233, 234, 235, 233, 238, 239, 249</p>	<p>Chairs (118, 123, 123A), Couches (123A, 134, 143, 205, 218, 239, coaches office); Curtains (221, 239); Outside furniture (233, 238); Cloth chair (Media); Book Shelf (234); Shelving replacement (235, 239, 249); stuffed animal (117, 138, 200, 205, 234); hanging paper (234, 236)</p>	<p align="center">X</p>			<p align="center">2/14/17</p>			
<p>13. No structural or physical gaps around exit doors</p>	<p>Media Center, Cafeteria</p>	<p>Door Strip in Media Center needs to be secured, Cafeteria has gap under doors</p>		<p align="center">X</p>	<p>Work #20015</p>	<p align="center">2/3/17</p>	<p>Job not complete</p>		

IEQ SCHOOL DATA BASE

School Name: River Hill High School

Principal: Kathryn McKinley

DATE: January 10, 2017

IEQ Team Leader: Napoleon A. Saunders, II

IEQ System Leader: Greg Macuilla

14. No improperly stored materials/chemicals	Admin Kitchen, 136A, 147, 153B 215, 217, 228, 244, 248,254, 256	Admin Kitchen -Household products, 136A, 147, 215, 217, 228, 256, media production room, 153B	X		None - Admin	2/14/17			
15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	217, 9th grade stairwell	loose tile (217), 9th grade stairwell		X	#20116/20117	2/4/17	2/13/17		
16. Barrier mats vacuumed well									
17. Fish tanks are clean and located away from vents/thermostats									
18. Waterproof barriers in place for plants and no standing water									
19. Sinks and fountains drain quickly and work properly including absence of leaks	Floor Drain (250, 252, cafeteria)	Cafeteria dishroom (rusted floor drains; water present on floor), Health room (brown water), clean sink and floor (café womens restroom)		X	Work # 20018	2/3/17	Job not complete		
20. No standing water in sinks, fountains, on counter	Cafeteria dishroom, Health room	Cafeteria dishroom (rusted floor drains; water present on floor), Health room (brown water)		X	Work # 20018	2/3/17			
21. Carpet dry nearby sinks, fountains	143, 233, 234	Rug removal (143, 233, 234); rugs not school property	X		None - Admin				
22. Soap and paper towels available									
23. All electrical outlets secure, no frayed wires on equipment	Art lobby, Auditorium	Electrical will need to address light panels, Art lobby light panel, auditorium		X	Work #20020	2/3/17			
24. All electrical cords secured and not extending across walkways	226A	226A (cord cover needed)							

IEQ SCHOOL DATA BASE

School Name: River Hill High School

Principal: Kathryn McKinley

DATE: January 10, 2017

IEQ Team Leader: Napoleon A. Saunders, II

IEQ System Leader: Greg Macuilla

37. Exterior veneer intact									
38. Outside lights working and intact									
39. Gutters and downspouts clear/working									
40. No stains from roof on outside walls									
41. Bins from garbage and recycling clearly marked									
42. Hard surfaces (sidewalks, etc.) cleared of any turf application									
43. Proper maintenance of planted beds and other vegetation									
44. Landscaping and turf look healthy and disease free									

COMMENTS:

Prohibited items not included above, 18" clearance needed (Rm 151, 215, 241, 244, S-100, Science office, Administration restroom, Admin Offices, Media Center); Prohibited appliances and furniture: Microwaves (Rm 100A, 102, 117, 123A, 132, 141, 142, 143, 147, 149, 152, 153B, 200, 206A, 215, 220, 239, 240, 241, Media Center, Studio, 206A, Coach's office, Teachers' planning D, Teachers' planning C, teacher planning B); Refrigerators (102, 117, 123A, 132A, 142, 147, 149, 152, 153B, 200, 222, 223A, 238, 239, 241, Coach's Office, Teachers' Planning D, Teacher's planning C); lamps (117, 121, 123, 219, 223, 235, 239, 240); coffee makers (117, 132, 233, 236, 240, teacher planning C); Toaster (Admin kitchen, Guidance workroom); Electric teapot (223A); fan (123, 142, 240, coaches office); heater (cafe office) **Administrative**

Tile replacement needed {stained or broken} (100, 123, 123A, 145, 149, 154, 200, 203, 204, 215, 216, 217, 218, 221, 223, 232A, 235, 236, 237, S-238, S-103, health room, 240, 241, 244, 246, 251, 254, 255, 9th grade stairwell, 9th grade hallway, Humanities stairwell, Humanities boys restroom, Administrative offices-AP, principal's office closet, administrative conference room, cafeteria, cafeteria hallway, kitchen, media center, production room, data clerk office, guidance, registrar office, health room, S-206B, above locker 1428 & 1560, near locker 1429, MST hallway, C-202, main gym, girls locker room and stairwell, weight room, restroom and storage, near C-131, Ives office, book room); Cord Protectors needed (117, 118, 148, 215, 217, 218, 219, 220, 221, 223, 226A, 231, 232, 233, 235, 237, 238, 240, 246, 249, 252, 253, 254, 255, 256) **Administrative**

IEQ SCHOOL DATA BASE

School Name: River Hill High School

Principal: Kathryn McKinley

DATE: January 10, 2017

IEQ Team Leader: Napoleon A. Saunders, II

IEQ System Leader: Greg Macuilla

<p>Fire Extinguishers throughout the building need to be inspected monthly Administrative</p>	<p>Plastic plants removal (117, 121, 123A, 140, 141, 143, 229, 234, 240, Admin restroom, media office, health room, Administrative</p>	<p>Fan repair (250); TV connector repair (251, 254); counter top (225A); Wall (S-207A) Light repair (104, 200, 205, 217, 235, C-153, team room, art hallway), Vent repair (102 hallway, 231, 244) Chipping paint (lounge), cracks in cynder block wall (S-207A), rusted vents (cafe hallway mens restroom) Facilities</p>							
<p>Sprinkler Repair (215, 216, 222, 241, 9th grade hall-locker 1280) Facilities</p>	<p>Items need to be moved (241 blocking heater, 244 blocking electrical panel, C-231, C-153, shelves (121), stool in 252. Administrative</p>	<p>Vents Cleaned (100, 100A, 204, 9th grade stairwell, 9th Grade Electrical room, All hallway vents, Electrical room-231, Humanities stairwell, Humanities restrooms, MST restrooms, S-253, cafeteria hallway restrooms, C-231, C-208A, auditorium, S-202, auxiliary gym, S-203, 203, main gym restrooms, S-103, gym hallway Administrative & Facilities</p>							
	<p>HVAC noise in guidance; no AC in weight room or locker room, HVAC repair (250,252) Facilities</p>	<p>Door Strip in Media Center needs to be secured, Cafeteria has gap under doors Facilities</p>							
		<p>Repair requests submitted: Work #20036 Fan Repair (250) Not completed; Work #20036 TV connectors (250, 251, 254) Completed 2/6/17; Work #20035 Light repair (104, 200, 205, 217, 235, C-153, team room, art hallway) Work #20034 AC in locker room/weight room Work in progress since 2/3/17; Work # 20033 Noise in Guidance No action noted; Work #20024 Light panel repair (215) Completed 2/9/17; Work #20023 Cord Protectors for multiple rooms Work in progress since 2/3/17; Work #20015 Door Strip (media and cafeteria) Work in progress since 2/3/17; Work #20124 Counter top (225A) Completed 2/16/17; Completed 2/6/17; Work #20120 Vent repair (102, 231, 244) Work in progress since 2/4/17; Work #20121 Chipping paint (lounge) Completed 2/13/17; Work #20123 Rusted vents (cafe hallway mens room) Work in progress</p>							
		<p>Repair requests submitted: Work #20119 Cord Cover needed (226A) Completed 2/6/17; Work #20125 Sprinkler repair (225A) Work in progress since 2/4/17;</p>							